

Probes



Probes are used to transfer liquid sample from a sample vial to the injection syringe by pressurizing the sample vial with helium.

GC and LC Probes

GC-111H	GC-111V	GC-311V	GC-411V	GC-311H	AS-300 (Perkin Elmer)
500031	500100	500100	500100	500441	500523
LC-241, 42 pos.		LC-241, 60 pos.			
500335		500301			