

Torx® Screwdriver Set

- · Set includes TR-10, TR-15, and TR-20.
- Ideal for performing routine maintenance on Agilent 6890 and 7890 GCs.



Description	qty.	cat.#	price
Torx Screwdriver Set	set	23034	



FID/Injector Cleaning Kit


The FID/Injector Cleaning Kit includes:

- Nylon tube brushes (1/8", 3/16", 1/4").
- · Pipe cleaner.
- Stainless steel tube brushes (3/8", 3/16", 1/4").
- · Stainless steel surface brush.
- · Stainless steel jet reamers.
- · Emery cloth.

Description	qty.	cat.#	price
FID/Injector Cleaning Kit	kit	20120	

Injector/Detector Plug Nuts

- Use to cap off an injector to isolate leaks.
- Use to cap off a detector for thermal cleaning.
- · Use to check a detector or make-up gas flow rate.
- · Use to cap off a detector and prevent hydrogen from accidentally diffusing into the oven from an unused detector base.







FID/NPD Adaptor Fitting

- · Easy to use, sturdy, compact stainless steel fitting.
- ¹/¹6-inch nut uses standard graphite or Vespel®/graphite ferrules.
- Wrench pad won't turn when installing a capillary column.
- Includes 1/4- and 1/16-inch stainless steel nuts, and 1/4-inch Vespel® and 0.4mm ID graphite ferrules.

Description	qty.	cat.#	price
FID/NPD Adaptor Fitting	kit	20884	



FID/NPD Capillary Adaptor Fitting for Agilent 5890/6890/6850 GCs

- · High-quality stainless steel construction.
- · Meets or exceeds original manufacturer's performance.

	Similar to			
Description	Agilent part #	qty.	cat.#	price
FTD/NPD Capillary Adaptor Fitting	19244-80610	ea	22077	



21301

Kit includes: replacement fitting, 1/4" nut, Vespel/graphite ferrule, 1/16" nut, 0.4 mm ID graphite ferrule, Siltek treated guide

Similar to			
Agilent part #	qty.	cat.#	price
	kit	21301	
	2-pk.	21302	
19233-20625	ea.	27192	
	5-pk.	27193	
G2397-20540	ea.	27190	
	5-pk.	27191	
	Agilent part # 19233-20625	Agilent part # qty. kit 2-pk. 19233-20625 ea. 5-pk. 62397-20540 ea. ea.	Agilent part # qty. cat.# kit 21301 2-pk. 21302 19233-20625 ea. 27192 5-pk. 27193 G2397-20540 ea. 27190

also available

Looking for more detector replacement parts? See page 271.







Mar 2011